

# Eversource Tree Removal List Scenic Roads New London NH

3/18/2021

<i>Tree #</i>	<i>Property Address</i>	<i>Pole #</i>	<i>Description</i>
1	Shaker st	603 /5 to 6	19" Ash declining large crown over phase, Ash yellows disease
2	Shaker st	603/6	13" Ash with Ash yellows disease
3	Shaker st	603/6 to 7	12"+ Maple rotted and weak
4	Shaker st	603/6 to 7	12"+ Maple dead
5	Shaker st	603/6to 7 across	16" red Maple with sapwood rot, parrellel to lines
6	Shaker st	603/6 to 7 across	8" Elm dead
7	Shaker st	603/7 to 8	11" Red Maple close to wires, bad joint in trunk
8	Shaker st	603/7 to 8	15" Ash in decline, Ash yellows disease
9	Shaker st	603/11 to 12	21" Ash heavy decline, Ash yellows disease
10	Camp Sunapee rd	686/11	18" Ash with Ash yellows disease
11	Camp Sunapee rd	686/11	18" Ash with Ash yellows disease
12	Davis Hill Rd	55B/2 to 3	16" Red Maple, seam in trunk, weak crown over wires
13	Davis Hill Rd	55B/3	22" Red Oak with dead crown
14	Davis Hill Rd	55B/3 across	17" Black Birch with mushrooms leaning to wires
15	Davis Hill Rd	55B/4	11" Beech with mushrooms, dead
16	Davis Hill Rd	55B/7	20" Maple with cavity rot, weak crown
17	Davis Hill Rd	55B/8	12.2" Ash dead, extensive rot and woodpecker holes. Across road
18	Davis Hill Rd	55B/ 11-12 across	16.1" Maple hollow with rot
19	Davis Hill Rd	55B/12 across	20.6" Birch dead
20	Davis Hill Rd	55B/21	11" Maple storm damaged with rot

# Eversource Tree Removal List Scenic Roads New London NH

3/18/2021

<i>Tree #</i>	<i>Property Address</i>	<i>Pole #</i>	<i>Description</i>
21	Davis Hill Rd	55B/ 24	14.2" Maple with rot seam in trunk
22	Davis Hill Rd	55B/ 25 to 26	12.9" Ash with Ash yellows disease
23	Davis Hill Rd	55B/27	29.2" Red Maple storm damaged, bad joint in trunk, crown over wires